

Pajaro Sunny Mesa Svc District

Don Rosa 136 San Juan Road Royal Oaks, CA 95076 **Monterey Bay Analytical Services** 4 Justin Court Suite D, Monterey, CA 93940

831.375.MBAS (6227)

www.MBASinc.com **ELAP Certification Number: 2385** 

Monday, March 27, 2023

## **Sample Results**

Lab Number: 230320 21-01

Collection Date/Time: 3/20/2023

11:10 Sample Collector: Farfan R

Client Sample #:

Received Date/Time: 3/20/2023 14:02

System ID: CA2700773

Coliform Designation: Special

Sample Description: Sunny Mesa WS, 18 Secondo Way											
Analyte	Method	<u>Unit</u>	Result Q	ualifier Dilution PQL	Analysis D	ate/Time	Analyst				
Chlorine Residual (Field)	External	mg/L	0.25	1	3/20/2023	11:10					
Coliform, E Coli	SM9223B-18hr	/100mL	Absent	1	3/20/2023	16:45	SB				
Coliform, Total	SM9223B-18hr	/100mL	Absent	1	3/20/2023	16:45	SB				

Comments:

Lab Number: 230320\_21-02

Collection Date/Time: 3/20/2023

11:40 Sample Collector: Farfan R Client Sample #:

Received Date/Time: 3/20/2023

14:02

System ID: CA2700773

Coliform Designation: Special

Sample Description: Sunny Mesa WS, 19 Bay Farms Rd											
<u>Analyte</u>	<u>Method</u>	<u>Unit</u>	<u>Result Qua</u>	lifier <u>Dilution</u> F	'QL Analysis Da	te/Time	<u>Analyst</u>				
Chlorine Residual (Field)	External	mg/L	0.45	1	3/20/2023	11:40					
Coliform, E Coli	SM9223B-18hr	/100mL	Absent	1	3/20/2023	16:45	SB				
Coliform, Total	SM9223B-18hr	/100mL	Absent	1	3/20/2023	16:45	SB				

Comments:

Report Approved by:

The results in this report are related only to the samples analyzed.

This certificate of analysis shall not be reproduced except in full, without written approval of the laboratory.

QC: Quality Control